



IMPERVIOUS BAG - WASHING RECOMMENDATIONS

DO NOT OVERBLEACH

Too much bleach may cause premature degradation and deterioration of the laminated fabric. Do not use more than 1.4l of 1% chlorine bleach per 45kg load (or proportions thereof)

Addition of ANTI-CHLOR at 1st or 2nd rinse after chlorine bleach operation will help eliminate residual bleach.

Use of oxygenated bleach is recommended.

DO NOT presoak in bleach.

DO NOT OVERLOAD.

Load equipment to no more than 80% of soiled weight.

DO NOT OVERDRY

Dry for approximately 10 minutes. Excessive drying temperature will cause damage and delamination of the bag fabric.

Set drying temperature at 65C (max 75C)..

Allow cool down of at least 8 – 10 minutes after drying cycle. Remove from the dryer as soon as cool down is complete and fold or store flat.

Bags may also hang dry.